


HP ADF roller replacement kit

for Color LaserJet Managed Flow MFP E57540; LaserJet Managed MFP E52545 - MFP E57540

Group	Printing Accessories
Manufacturer	HP
Manufacturer item no.	B5L52A
EAN/UPC	0888793231203



Description

HP - ADF roller replacement kit - for Color LaserJet Managed Flow MFP E57540; LaserJet Managed MFP E52545, MFP E57540

Main features

Product Description	HP - ADF roller replacement kit
Product Type	ADF roller replacement kit
Designed For	Color LaserJet Managed Flow MFP E57540, MFP M577; LaserJet Enterprise MFP M527, MFP M577, MFP M775; LaserJet Enterprise Flow MFP M527, MFP M577; LaserJet Managed MFP E52545, MFP E57540, MFP M527, MFP M577; LaserJet Managed Flow MFP E52545, MFP M527

Extended details

	General
Product Type	ADF roller replacement kit
	Compatibility Information
Designed For	HP Color LaserJet Managed Flow MFP E57540c, MFP M577cm HP LaserJet Enterprise MFP M527dn, MFP M527f, MFP M577dn, MFP M577f, MFP M775z HP LaserJet Enterprise Flow MFP M527c, MFP M527z, MFP M577c, MFP M577z HP LaserJet Managed MFP E52545dn, MFP E57540dn, MFP M527dnm, MFP M577dnm HP LaserJet Managed Flow MFP E52545c, MFP M527cm

Technical data © 1WorldSync. Subject to technical modifications and errors.