



Lexmark™

Lexmark Type 06 - (220 - 240 V)

printer maintenance fuser kit - for Lexmark MX710 - MX711 - MX810 - MX811 - MX812

Group	Printing Accessories
Manufacturer	Lexmark
Manufacturer item no.	40X8426
EAN/UPC	0734646497985

Description

The operator panel displays the message 80 "replace maintenance kit" at required maintenance intervals. You must replace the fuser, transfer roller, pick roller, and separation roller at this interval to maintain the print quality and reliability of the printer.

Main features

Product Description	Lexmark Type 06 - printer maintenance fuser kit
Product Type	Printer maintenance fuser kit (220 - 240 V)
Printing Technology	Laser
Compatible with	Lexmark MX710, MX711, MX810, MX811, MX812

Extended details

Consumable

Consumable Type	Printer maintenance fuser kit (220 - 240 V)
Printing Technology	Laser

Compatibility Information

Compatible with	Lexmark MX710de, MX710dhe, MX711de, MX711dhe, MX711dte, MX711dthe, MX810de, MX810dfe, MX810dme, MX810dpe, MX810dte, MX810dtfe, MX810dtme, MX810dtpe, MX810dxe, MX810dxfe, MX810dxme, MX810dxpe, MX811de, MX811dfe, MX811dme, MX811dpe, MX811dte, MX811dtfe, MX811dtme, MX811dtpe, MX811dxe, MX811dxfe, MX811dxme, MX811dxpe, MX812de, MX812dfe, MX812dme, MX812dpe, MX812dte, MX812dtfe, MX812dtme, MX812dtpe, MX812dxe, MX812dxfe, MX812dxme, MX812dxpe
-----------------	--